

Field Report

Project: juminda_0006

Type: Single Line

Opeator: hannes


Company: Company

Time: Fri Oct 02 12:08:13 GMT+03:00 2020


Markers HF

"Proposed Excavation" (White) (APWA)		
Index	Coordinates	Depth
1	59.5275068333N, 25.5786675000E	6.08 [m]
2	59.5274211667N, 25.5770840000E	2.39 [m]
3	59.5273476667N, 25.5760625000E	2.46 [m]
4	59.5270753333N, 25.5718951667E	14.36 [m]
5	59.5270888333N, 25.5719803333E	14.05 [m]
6	59.5268018333N, 25.5684275000E	4.33 [m]


Screenshots HF




Screenshot of file: juminda_0002
Including markers: [1]




Screenshot of file: juminda_0002
Including markers: [2]




Screenshot of file: juminda_0003
Including markers: [1, 2]




Screenshot of file: juminda_0006
Including markers: [1]




Screenshot of file: juminda_0006
Including markers: [2]



Screenshot of file: juminda_0006
Including markers: [3]



Screenshot of file: juminda_0006
Including markers: [4, 5]



Screenshot of file: juminda_0006
Including markers: [6]

